

## LEAK SURVEY REPORT

Table 1 – Summary of Leak Survey

<b>Underground Gas Storage Facility</b>	<b>Aboveground Leaks Found</b>	<b>Leaks Repaired</b>	<b>Leaks Pending</b>
Aliso Canyon	66 <sup>1</sup>	66	0
Goleta	17 <sup>2</sup>	17	0
Honor Rancho	14	14	0
Playa Del Rey	3	3	0
Montebello	6	6	0

Table 2 – Leak Survey Result Details

<b>Leak Classification</b>	<b>Underground Storage Facility</b>					<b>Total Aboveground Leaks Found</b>	<b>Total Leaks Repaired</b>
	<b>Aliso Canyon</b>	<b>Goleta</b>	<b>Honor Rancho</b>	<b>Playa Del Rey</b>	<b>Montebello</b>		
Minor Non-Hazardous <sup>3</sup>	66	17	13	3	6	105	105
Non-minor Non-Hazardous <sup>4</sup>	0	0	1 <sup>5</sup>	0	0	1	1
Hazardous	0	0	0	0	0	0	0

<sup>1</sup> This does not include a minor detection of gas in one location that is currently being monitored and investigated. Based upon field investigation, SoCalGas does not believe this detection constitutes a leak.

<sup>2</sup> This does not include a minor detection of gas in one location which was determined not to be storage gas and was verified by field survey and testing to be naturally occurring field gas.

<sup>3</sup> A leak classified as minor non-hazardous can be repaired by tightening, adjustment, lubrication or replacement of parts or piping. The leak does not pose an immediate danger to public or property, or the environment.

<sup>4</sup> A leak classified as non-minor non-hazardous is not able to be promptly repaired by tightening, adjustment, lubrication but does not pose an immediate danger to public, property or the environment.

<sup>5</sup> Leak from a compressor unit discharge valve stem, requiring replacement of the valve which was completed.